




**Concern-**


Our homeowner moved into this home and the \$4,000.00 grill was already there. Unfortunately, the grill was neglected and not working. Should the homeowner scrap the grill and purchase a new one or should he pay to have it refurbished?








**We will remove as much of the surface rust on the cooking grids as possible. These are coated steel cooking grids. Once the coating has been damaged, moisture through grease, fat, sauce, etc. penetrates to the metal and contributes to the acceleration of rust.**



**Even though these burners show tremendous rust, they still fire up. Let's try to keep them through Labor Day as these burners are more than \$100.00 each.**





**This burner cover is rusted throughout.**



**This damaged rivot is scratching the grill on the inside.**



## Estimate of Service and Repairs

- 1- Grill Cleaning (built-in grill)- \$295.00
  - 2- (3) Burners @ \$124.12 Total- \$372.36
  - 3- (3) Cooking Grids @ \$98.27 Total- \$294.81
  - 4- (3) Burner Covers @ \$42.91 Total- \$128.73
  - 5- (2) Gas valves @ \$49.17 Total- \$98.34
  - 6- (5) Rotary Piezo spark generators @ \$19.66 Total- \$98.30
  - 7- (5) Sparking electrodes @ \$18.56 Total- \$92.80
  - 8- (1) Smoker box burner @ \$34.51 Total- \$34.51
  - 9- (1) Shipping for all parts @ \$20.00 Total- \$20.00
  - 10- (1) Labor to install all parts @ \$50.00 Total- \$50.00
- Total for service- cleaning and replacement parts- \$ 1,484.85

### **Result**

Homeowner contracted with Sparkle Grill Cleaning to refurbish his built-in grill. After installing new components, such as burners, cooking grids and burner covers, and a comprehensive cleaning, the homeowner has essentially a new \$4,000.00 built-in grill for less than \$1,500.00. He is thrilled with the outcome and with his tremendous savings.

Please see the following before and after pictures.





**Before Picture**



**After picture**

